

To Clean Environment Commission

**Location Options for Bipole
Converter Stations near Winnipeg**


Part 2

Dennis Woodford P.Eng.


5th March, 2013

% of BPII Equipment Replaced vs Years of Service

% OF EQUIPMENT REACHING LIFETIME REPLACED EVERY TIME




Dorsey Converters BP I & BP II



Dorsey Converters BP I Only



Example: Sylmar Converter



Example: Sylmar Converter


Sylmar West

2000 MW


Sylmar East

New valves,
transformers, controls,
cooling (2004)


DC transmission de-
rated to 2000 MW




Example: Sylmar Converter




High level diagram of Manitoba Hydro's southern system DC inverters and tie lines (CIGRE August 2012 paper B4-103)



New BP II Inverter at Riel



New BP II Inverter at Riel




HVDC Transmission & Wind

- Tower failures usually limited to short distances
- Tower, conductor, insulator inventory necessary
- Good restoration practice essential
- Will severe wind occur in a forest?




Iced Transmission Insulator



Icing Conditions

- Temperature October 5, 2012 ice storm SE Manitoba (Steinbach temperatures: Max 1.9 Deg C, Min -0.1 Deg C)
- Ice storm impacts Manitoba and Saskatchewan February 9, 2009 (Brandon temperatures: Max 0.8 Deg C, Min -5.6 Deg C)


Typical altitude temperature profile associated with freezing rain



E.L. Lecomte, A.W.Wang, J.W. Russell, "ICE STORM '98", Institute for Catastrophic Loss Reduction, Research Paper Series – No. 1.

<http://cip.management.dal.ca/publications/ICE%20STORM%2098.pdf>

BP I & II Conductor Temperatures




Converter Controls

- Today BP I and BP II controls are analogue (30 year old technology) which eventually must be replaced
- Tomorrow BP I, BP II and Bipole III controls will be digital – State of the art – Will facilitate locating BP II at Riel with fast, redundant fibre optic telecommunications

HVDC Transmission Line Resonance

- Resonance (a sustained oscillation of DC line voltage and current) is common and expected in designing new HVDC Transmission Lines
- With HVDC Engineers in Manitoba Hydro, Teshmont Consultants and HVDC Equipment Suppliers, HVDC resonance problems can be remedied as have been done in the past



LAKE
MANITOBA

St. Ambrose Beach
Provincial Park

Oak Hammock
Marsh
WMA

Selkirk

Birds Hill
Provincial
Park

< 70 km O/H

50 km Cable

100 km's

60 km's

70 km's

230 km's

Potential Switch of re-connected BPII Line

Potential Switch of re-connected BPII Line

Portage la Prairie


Daer

Winnipeg

Riel



— Existing
— The proposed
/// Decommissioned



Conclusions Part 2

- Bipole II inverter could be located at Riel with little disruption of power
- Three inverters at three different locations around Winnipeg increases reliability
- Ice storms can be managed effectively to prevent DC transmission line failure
- Wind storm failures must be anticipated with inventory and heavy lift helicopters

Thank you

